

REPORTED INCIDENTS

Date: March 23, 2018

Location: 2980 Westbound TX 114 Frontage Road (near Trophy Wood Drive)

Occurrence: Sanitary sewer overflow with an estimated volume of 10,250 gallons was observed from 1:57 PM to 3:30 PM on March 23, 2018.

Cause and Effect: A contractor working on a project at the specified location excavated without first calling for line locate and hit our 10-inch force main. Water from the site ran across the frontage road into a storm drain and ultimately towards an unnamed tributary into Marshall Creek.



Corrective Actions: Lift Station #3 was shut down and a vacuum truck removed all standing water in the area. Once the surcharge was eliminated, emergency crews repaired the force main. Downstream areas were monitored throughout the weekend and no fish kills were observed. Lime was applied to the affected soils. The contractor was reminded of the requirement to seek underground utility locates prior to excavation.

Reporting: The overflow was reported to TCEQ verbally on 3/23/2018 and in writing within 5 days.