

REPORTED INCIDENTS

Date: March 29, 2018

Location of Incident: 1124 Trophy Club Drive, Trophy Club Texas

Occurrence: Sanitary sewer overflow from a manhole at 1124 Trophy Club Drive was reported at 8:15 PM. The overflow released an estimated volume of 1000 gallons into the location's storm drain.

Cause and Effect: Roots found in the line caused the backup.



Corrective Actions: Eliminated overflow at 9:45 PM with a vacuum truck. Rodded line to sufficiently maintain flow. Monitored storm drain and manhole throughout the weekend. Observed no downstream impacts.

Monday, April 2 – Attempted to remove roots using a root cutter. Line had to be excavated after root cutter became stuck. Excavation revealed a break in the top section of clay sewer pipe which transitioned to PVC pipe allowing roots to enter. Replaced PVC in entire section.

Reporting: The overflow was reported to TCEQ verbally on 3/29/2018 and in writing within 5 days.