

Water Quality Noncompliance Notification

See back of Form for Guidance for Completion

Unauthorized Discharge

Reportable Effluent Violation

Other

General Information

Entity Name: Trophy Club Municipal Utility District No.1

Telephone No (#####): (682) 831-4600

Permittee

TCEQ Region: R4 - DFW

County: Denton

*Permit Number: TX0055735

Subscriber

Noncompliance Summary

Description and Cause of Noncompliance (include location, discharge route, and estimated volume of unauthorized discharge):

On August 31, 2018 at 4:16pm we received a call of a sewer backup at 6 Straight Creek Ct. in Trophy Club, TX. Field personnel were immediately dispatched to location and arrived on-site at 4:33pm. The blockage was released at 7:00pm. Field personnel estimated 1,000 gals of sewer overflowed into storm drain that leads to a pond on the golf course. This pond was monitored for any changes. Pictures were taken of this area to monitor for any problems. No adverse affects were found. Called was placed to Region 4 office and message was left, informing that we had a spill at 9:28pm on August 31, 2018.

Duration:

Start Date: 8/31/18

End Date: 8/31/18

Or

Date Expected to be Corrected: 8/31/18

Time: 4:16pm

Time: 7:00pm

Potential Danger to Human Health and Safety or the Environment:

No dangers were found.

Actions Taken

Monitoring Data: Data should be attached or submitted to TCEQ when available.

Field Measurements

Laboratory Samples

Fish Kill (If yes, estimated number killed):

Yes No

Yes No

Yes No

Actions Taken to Mitigate Adverse Effects:

Lime was placed on any areas in yards that sewer may have come in contact with.

Actions Taken to Correct the Problem and Prevent Recurrence:

The sewer lines will be cleaned in this area and monitored and treated for grease buildup.

Verification Information

Information Reported By (Name/Title): Mike McMahon

Date Reported: Sep 4, 2018

Signature:



Note: If this form is being used for a 5-day written report, a copy of the form should be sent to the TCEQ Region Office, and the original to: TCEQ, Compliance Monitoring Team (MC224), Enforcement Division, P.O. Box 13087, Austin, TX 78711-3087.

* If the noncompliance is an unauthorized discharge from a wastewater collection system, use the permit number of the treatment plant to which the collection system is tied. If you are uncertain of this permit number, you may call the TCEQ Regional Office for assistance.